

Contents [Telcordia SR-TSY-001425-Documentation Information](#)

Special Report Notice Of Disclaimer	iii
List of Figures	vi
List of Tables	vii
1 Introduction	
2 Test Sequence	
3 Test Results and Failure Analysis	
3.1 Manufacturer A	3-1
3.2 Manufacturer B	3-3
3.3 Manufacturer C	3-4
3.4 Manufacturer D	3-4
3.5 Manufacturer F	3-5
3.6 Manufacturer G	3-5
3.7 Manufacturer H	3-5
4 Conclusion	
Appendix A: Calculation of Fiber Stress	
Appendix B: References	

List of Figures

Figure 1	Broken Fiber Inside the Package of A-a1	A-5
Figure 2	Broken Fiber Inside the Package of A-a2	A-5
Figure 3	Cross Section of Fiber Pigtail System	A-6
Figure 4	Cracked Solder Bond Permitting the Fiber Moved into the Package . .	A-7
Figure 5	Jacket Shrinkage	A-8
Figure 6	Extra Fiber Was Pushed into the Package and Contacted the Laser . .	A-9
Figure 7	New Laser Module Design from Manufacturer A	A-10
Figure 8	Biconic Connector	A-11
Figure 9	Thermoelectric Cooler Failures	A-12

List of Tables

Table 1	Temperature Cycling Test Samples	A-3
Table 2	Temperature Cycling Test Results	A-4