
Generic Requirements for Optical Loss Test Sets

Contents

Preface	Preface-1
1. Introduction	1-1
1.1 Document Description	1-1
1.2 Summary of Significant Changes to TA-NWT-000198, Issue 4	1-1
1.3 Organization	1-2
1.4 Requirements Terminology	1-2
1.5 Requirement Labeling Conventions	1-3
1.5.1 Numbering of Requirement and Related Objects	1-3
1.5.2 Requirement, Conditional Requirement, and Objective Object Identification	1-3
1.6 Technical Feature/Function Testing	1-3
1.7 Quality and Reliability Analysis/Audit	1-4
1.7.1 Technical Quality Analysis/Audit	1-4
1.7.2 Technical Reliability Analysis/Audit	1-4
1.7.3 Other Activities	1-5
2. General Information	2-1
2.1 Product Definition	2-1
2.1.1 Principles of Operation	2-1
2.1.1.1 Optical Loss Measurements	2-1
2.1.1.2 Optical Reflection Measurements	2-3
2.1.2 Performance	2-4
2.1.3 OLTS Components	2-5
2.2 Applications and Uses	2-6
2.2.1 Optical Loss Measurements	2-6
2.2.2 Optical Reflection Measurements	2-6
2.3 Operating Environment	2-7
3. General Requirements	3-1
3.1 Display and Control Features	3-1
3.2 Operational Features	3-1
3.3 Unit Powering Features	3-3
3.4 Input/Output Port Features	3-4
3.5 Mechanical Design Features	3-4
3.6 Calibration and Maintenance Features	3-5
3.7 Product Information	3-6
3.7.1 Documentation	3-6
3.7.2 Performance Specification Sheet	3-6

3.8	Product Marking and Packaging	3-8
3.8.1	Product Marking.....	3-8
3.8.2	Packaging for Shipment from Supplier.....	3-8
3.9	Safety Features	3-8
4.	Specific Requirements	4-1
4.1	Operational Requirements.....	4-1
4.1.1	Transmitter Wavelength.....	4-1
4.1.2	Transmitter Stability.....	4-1
4.1.3	Transmitter Output Power.....	4-2
4.1.4	Detector Integrity	4-2
4.1.5	Detector Stability	4-2
4.1.6	Minimum and Maximum Response Power.....	4-3
4.1.7	Measurement Range.....	4-4
4.1.8	Measurement Accuracy.....	4-4
4.1.9	Measurement Repeatability.....	4-5
4.1.10	Measurement Time.....	4-5
4.2	Mechanical Design Criteria.....	4-6
4.2.1	Shipment from Manufacturer.....	4-6
4.2.2	Local Transportation	4-6
4.2.3	During Use	4-6
4.2.4	Vibration Test.....	4-6
4.3	Power Criteria	4-6
4.4	Environmental Criteria.....	4-7
4.4.1	Non-Operating Environment.....	4-7
4.4.2	Operating Environment.....	4-7
4.5	Safety Criteria	4-7
5.	Performance Verification and Test Procedures	5-1
5.1	Operational Criteria.....	5-1
5.1.1	Transmitter Wavelength.....	5-1
5.1.2	Transmitter Stability.....	5-2
5.1.2.1	Power Stability: Long Term	5-2
5.1.2.2	Power Stability: Temperature	5-3
5.1.2.3	Power Stabilization Time.....	5-3
5.1.2.4	Secondary Power Stabilization Time.....	5-3
5.1.2.5	Transmitter Optical Output Power Repeatability	5-3
5.1.3	Transmitter Output Power.....	5-3
5.1.4	Detector Integrity	5-4
5.1.5	Detector Stability	5-4
5.1.6	Minimum and Maximum Response Power.....	5-5
5.1.7	Measurement Range.....	5-6
5.1.8	Measurement Accuracy.....	5-6
5.1.8.1	Reflection Measurement Accuracy.....	5-6
5.1.9	Measurement Repeatability.....	5-7

5.1.10	Measurement Time.....	5-7
5.2	Mechanical Design Criteria.....	5-8
5.2.1	Shock During Transportation.....	5-8
5.2.1.1	Free Fall Drop.....	5-8
5.2.1.2	Free Fall Corner Drop.....	5-8
5.2.2	Shock During Use	5-8
5.2.3	Vibration Test.....	5-9
5.3	Power Test.....	5-9
5.4	Environmental Criteria.....	5-9
5.4.1	Non-Operating Environment.....	5-9
5.4.2	Operating Environment.....	5-10
5.5	Safety.....	5-10
References	References-1
Glossary	Glossary-1

List of Figures

Figure 2-1.	Typical Test Configuration to Measure Optical Power Loss	2-2
Figure 2-2.	General Block Diagram of an OCWR	2-4
Figure 5-1.	Detector Stability Test Setup	5-4
Figure 5-2.	Setup for Reflection Measurement Accuracy Test	5-6
Figure 5-3.	OLTS Power Test	5-9

List of Tables

Table 4-1.	Wavelength Characteristics of the Transmitter	4-1
Table 4-2.	Response Power Requirements.....	4-3
Table 4-3.	Response Power Objectives.....	4-3
Table 4-4.	Measurement Range Requirements	4-4