

Contents

[Telcordia GR-264 - Documentation Information](#)

Preface	xiii
1 Introduction	
1.1 Document Description	1-1
1.2 Organization	1-1
1.3 Analysis Criteria	1-2
1.4 Reliability Audit	1-3
1.5 Definitions of Key Terms	1-4
1.6 Reasons for Reissue and Major Changes	1-5
1.6.1 Reasons for Reissue	1-5
1.6.2 Major Changes from TR-TSY-000264, Issue 1	1-6
1.6.2.1 Usage-Sensitive Criteria	1-6
1.6.2.2 Measurement of Angled Cleaves	1-6
1.6.2.3 Cleaving of Specialty Fibers	1-6
1.6.2.4 Cleaving in Various Environments	1-7
1.6.2.5 Classification of Defects	1-7
1.6.2.6 Classification of Cleave Quality	1-7
1.6.2.7 Electrical Requirements	1-7
1.6.2.8 Thermal Shock	1-7
2 General Information	
2.1 Product Description	2-1
2.1.1 Types of Splices	2-1
2.1.1.1 Fusion Splices	2-1
2.1.1.2 Mechanical Splices	2-1
2.1.2 Processes for Preparing Fiber Ends	2-2
2.1.3 The Cleaving Process	2-2
2.1.3.1 Producing a Cleave	2-2
2.1.3.2 Characterizing a Cleave	2-2
2.1.3.3 Calculation of Loss Contribution From Angled Cleave	2-3
2.1.4 Reflectance	2-5
2.1.5 Low-Precision Cleavers	2-5
2.1.6 Multi-Fiber Splices	2-7
2.1.7 Specialty Fibers	2-8
2.2 Product Applications	2-8
2.3 Product Testing	2-9
2.3.1 Reporting of Test Data	2-9
2.3.2 Number of Test Samples	2-9
2.4 Supplier-Provided Data	2-9
3 General Requirements and Objectives	
3.1 Documentation	3-1

3.1.1 Practices	3-1
3.1.2 Workcenter Information Package	3-1
3.2 Marking, Packaging, and Shipping	3-2
3.2.1 Marking	3-2
3.2.2 Packaging and Shipping	3-2
3.3 Equipment: General Requirements and Objectives	3-3
3.3.1 Carrying Case	3-3
3.3.2 Chemicals and Moisture	3-3
3.3.3 Product Information	3-3

4 Performance Requirements and Objectives

4.1 Criteria Applicable to Product As-Received	4-2
4.1.1 Criteria Applicable to All Cleavers	4-2
4.1.2 Cleave Angle Criteria	4-3
4.1.2.1 High Precision Perpendicular Cleavers	4-4
4.1.2.2 High Precision Angled Cleavers	4-4
4.1.2.3 Low-Precision Cleavers	4-5
4.1.3 Multi-Fiber Cleavers	4-6
4.1.3.1 Fiber-Count and Ribbon Construction Tolerance	4-6
4.1.3.2 Multi-Fiber Perpendicular Cleavers	4-7
4.1.3.3 Multi-Fiber Angled Cleavers	4-8
4.2 Mechanical and Storage Environments Criteria	4-8
4.2.1 Shock	4-8
4.2.2 Storage Environment	4-9
4.2.3 Electrical Requirements	4-9
4.3 Fiber Cleaving Environmental Conditions	4-10
4.3.1 Low Temperature	4-10
4.3.2 High Temperature, High Humidity	4-10
4.3.3 High Temperature, Low Humidity	4-11
4.3.4 Operation When Wet	4-11
4.3.5 Exposure to Dust and Vibration	4-11
4.4 Cleaver Extended Operation	4-11

5 Measurement of Cleave Angle Test Procedure

5.1 Interferometry	5-1
5.1.1 Basic Principle	5-1
5.1.2 Defects	5-3
5.1.3 Measurement Error	5-4
5.2 Beam Deflection	5-5
5.2.1 Basic Principle	5-5
5.2.2 Description of the Measurement Technique	5-8
5.3 Cleaving Schedule	5-10

6 Lists of Requirements and Objectives

Appendix A: References

Note	A-3
To Contact Telcordia Customer Service or to Order Documents	A-3
To Order Documents From Within Telcordia (Employees Only)	A-3
To Request Telcordia Testing Services	A-3

List of Figures

Figure 2-1	Core Separation Due to Angled Cleave	2-4
Figure 2-2	Temperature Dependence of Reflection From Mechanical Splices	2-5
Figure 2-3	Effect of Cleave Angle on Fusion Splice Loss for Long-Duration Arcs	2-6
Figure 2-4	Cleave Lengths in Ribbon Fiber	2-8
Figure 5-1	Schematic Diagram of Interferometer	5-2
Figure 5-2	Measurement of Cleave Angle by Interferometry	5-3
Figure 5-3	Distinguishing Protruding and Non-Protruding Defects	5-4
Figure 5-4	Basic Principle of Beam Deflection Technique	5-6
Figure 5-5	Cleave Angle as Function of Beam Displacement	5-8
Figure 5-6	Schematic Diagram of Beam Deflection Measurement Apparatus .	5-9

List of Tables

Table 2-1	Worst-Case Loss Due to Core Separation from Cleave Angle . . .	2-4
Table 4-1	Summary of Cleave Angle Criteria	4-4
Table 5-1	Cleave Angle as Function of Beam Displacement	5-7
Table 5-2	Cleaving Schedule	5-10