

Contents

List of Figures	x
List of Tables	xi
1. Introduction	1-1
1.1 The Purpose and Scope of Document	1-1
1.2 Requirements Terminology	1-2
1.3 Requirement Labeling Conventions	1-3
1.3.1 Numbering of Requirement and Related Objects	1-3
1.3.2 Requirement, Conditional Requirement, and Objective Object Identification	1-3
1.4 Organization	1-4
2. General Information	2-1
2.1 Fiber Optic Filter Types	2-1
2.2 Fiber Optic Filter Technology	2-2
2.2.1 Dielectric Interference Coatings	2-2
2.2.2 Fiber Optic Bragg Gratings	2-2
2.2.3 Fiber Fabry-Perot Filters	2-3
2.3 Fiber Optic Filter Applications	2-3
2.3.1 Fiber Optic Filters in EDFAs	2-4
2.3.1.1 Optical Pump Filters for EDFAs	2-4
2.3.1.2 EDFA Pump Power Suppression/Recycling	2-5
2.3.1.3 ASE Suppression in EDFAs	2-5
2.3.1.4 Gain Flattening in EDFAs	2-6
2.3.2 Fiber Optic Filters in Multiwavelength Networks	2-6
2.3.2.1 Wavelength Add-Drop Multiplexers (WADMs)	2-8
2.3.3 Fiber Optic Filters in Remote Fiber Test Systems	2-10
2.3.4 Non-Intrusive Remote Fiber Testing	2-10
2.3.4.1 Specific Testing Techniques	2-10
3. General and Design Criteria	3-1
3.1 Documentation	3-1
3.1.1 General Documentation	3-1
3.1.2 Workcenter Information Package	3-3
3.2 Marking, Packaging and Shipping	3-3
3.3 Physical Design Criteria	3-3
3.3.1 Optical Fiber	3-3
3.3.2 Optical Connectors	3-5
3.3.3 Materials	3-5
3.3.3.1 Toxicity	3-5
3.3.3.2 Corrosion Resistance	3-5
3.3.3.3 Dissimilar Metals	3-6
3.3.3.4 Fungus Resistance	3-6
3.3.3.5 Flammability	3-6
3.3.4 Safety	3-6
3.3.5 Mounting	3-7

- 3.3.5.1 Central Office Location 3-7
- 3.3.5.2 Outside Plant Location 3-9
- 4. Performance Criteria 4-1
 - 4.1 Optical Criteria 4-3
 - 4.1.1 Optical Bandwidth/Passband and Center Wavelength 4-3
 - 4.1.2 Insertion Loss 4-4
 - 4.1.3 Flatness 4-4
 - 4.1.4 Wavelength Isolation or Optical Crosstalk 4-5
 - 4.1.5 Reflectance 4-6
 - 4.1.6 Polarization-Dependent Loss (PDL) 4-6
 - 4.1.7 Other Optical Criteria for Dense WDM Systems 4-7
 - 4.1.7.1 Center Wavelength Misalignment 4-7
 - 4.1.7.2 Polarization Sensitivity of Center Wavelength
and Optical Bandwidth 4-7
 - 4.1.7.3 Temperature Sensitivity 4-8
 - 4.2 Environmental Criteria 4-8
 - 4.2.1 Operating Environment 4-9
 - 4.2.2 Non-Operating Environment 4-10
 - 4.2.3 Shock Criteria 4-10
 - 4.2.3.1 Shipment from Manufacturer 4-10
 - 4.2.3.2 Local Transportation 4-10
 - 4.2.3.3 During Use 4-10
 - 4.2.4 Vibration Test 4-10
 - 4.2.5 Airborne Contaminants 4-11
 - 4.2.6 Flex Test 4-11
 - 4.2.7 Twist Test 4-12
 - 4.2.8 Side Pull 4-12
 - 4.2.9 Cable Retention 4-12
- 5. Performance Verification/Test Procedures 5-1
 - 5.1 Optical Testing 5-1
 - 5.1.1 Optical Passband/Bandwidth 5-2
 - 5.1.2 Insertion Loss 5-3
 - 5.1.3 Flatness 5-3
 - 5.1.4 Wavelength Isolation or Optical Crosstalk 5-3
 - 5.1.5 Reflectance 5-4
 - 5.1.6 Polarization-Dependent Loss (PDL) 5-4
 - 5.1.7 Other Optical Criteria for Dense WDM Systems 5-4
 - 5.1.7.1 Center Wavelength Misalignment 5-4
 - 5.1.7.2 Polarization Sensitivity of Center Wavelength
and Optical Bandwidth 5-4
 - 5.1.7.3 Temperature Sensitivity 5-4
 - 5.2 Environmental Testing 5-4
 - 5.2.1 Operating Environment 5-5
 - 5.2.2 Non-Operating Environment 5-5
 - 5.2.3 Shock Tests 5-5
 - 5.2.3.1 Shipment from Manufacturer 5-5

- 5.2.3.2 Local Transportation 5-5
- 5.2.3.3 In Use 5-6
- 5.2.4 Vibration Test 5-6
- 5.2.5 Airborne Contaminants Test 5-6
- 5.2.6 Flex Test 5-6
- 5.2.7 Twist Test 5-6
- 5.2.8 Side Pull 5-6
- 5.2.9 Cable Retention 5-7
- 6. Reliability and Quality Assurance Program 6-1
 - 6.1 Reliability Assurance Requirements Philosophy 6-1
 - 6.2 Overview of Reliability Assurance 6-1
 - 6.3 Qualification Criteria 6-3
 - 6.3.1 Characterization 6-3
 - 6.3.2 Reliability Tests 6-4
 - 6.3.3 Failure Rate Prediction 6-8
 - 6.3.4 Optical Adhesives 6-11
 - 6.3.5 Quality Assurance and Lot Controls 6-11
 - 6.3.5.1 Visual Inspection 6-12
 - 6.3.5.2 Optical Testing 6-12
 - 6.3.5.3 Stress Screening 6-12
 - 6.3.6 Optical Adhesives 6-13
 - 6.3.7 Optical Connectors 6-13
 - 6.3.8 Optical Fiber 6-13
 - 6.4 Quality and Reliability Criteria 6-13
 - 6.4.1 Reliability Assurance 6-14
 - 6.4.2 Quality Technology Program 6-15
- Appendix A: References A-1
- Appendix B: Acronyms B-1
- Appendix C: Glossary C-1

List of Figures

Figure 2-1	Block diagram of a fiber optic filter	2-1
Figure 2-2	Forming a grating structure in an optical fiber	2-3
Figure 2-3	1480 nm pump filter in an EDFA	2-4
Figure 2-4	Pump power suppression using a longpass filter at the amplifier output	2-5
Figure 2-5	Fiber Bragg-grating filter for pump power reflection	2-5
Figure 2-6	Broadcast-and-select WDM star network	2-7
Figure 2-7	(a) Wavelength-routing WDM network and (b) associated wavelength assignment table	2-8
Figure 2-8	WADM using optical circulators	2-9
Figure 2-9	WADM using dielectric thin film bandpass filters	2-9
Figure 2-10	General Schematic: Non-Intrusive Testing of Optical Network	2-10
Figure 2-11	WDM/Filter Technique for Non-Intrusive Testing	2-11
Figure 2-12	Coupler/Filter Technique for Non-Intrusive Testing	2-11
Figure 3-1	Generic Frame Mountable Filter	3-7
Figure 3-2	Possible Filter Location in a Central Office	3-8
Figure 3-3	Example of a Filter Mounted in an OSP Closure	3-9
Figure 6-1	Elements of a Comprehensive Reliability Assurance Program	6-3

