

Contents

Telcordia GR-2883 - Documentation Information

List of Figures	x
List of Tables	xi
1. Introduction	1-1
1.1 The Purpose and Scope of Document	1-1
1.2 Requirements Terminology	1-2
1.3 Requirement Labeling Conventions	1-3
1.3.1 Numbering of Requirement and Related Objects	1-3
1.3.2 Requirement, Conditional Requirement, and Objective Object Identification	1-3
1.4 Organization	1-4
2. General Information	2-1
2.1 Fiber Optic Filter Types	2-1
2.2 Fiber Optic Filter Technology	2-2
2.2.1 Dielectric Interference Coatings	2-2
2.2.2 Fiber Optic Bragg Gratings	2-2
2.2.3 Fiber Fabry-Perot Filters	2-3
2.3 Fiber Optic Filter Applications	2-3
2.3.1 Fiber Optic Filters in EDFAs	2-4
2.3.1.1 Optical Pump Filters for EDFAs	2-4
2.3.1.2 EDFA Pump Power Suppression/Recycling	2-5
2.3.1.3 ASE Suppression in EDFAs	2-5
2.3.1.4 Gain Flattening in EDFAs	2-6
2.3.2 Fiber Optic Filters in Multiwavelength Networks	2-6
2.3.2.1 Wavelength Add-Drop Multiplexers (WADMs)	2-8
2.3.3 Fiber Optic Filters in Remote Fiber Test Systems	2-10
2.3.4 Non-Intrusive Remote Fiber Testing	2-10
2.3.4.1 Specific Testing Techniques	2-10
3. General and Design Criteria	3-1
3.1 Documentation	3-1
3.1.1 General Documentation	3-1
3.1.2 Workcenter Information Package	3-3
3.2 Marking, Packaging and Shipping	3-3
3.3 Physical Design Criteria	3-3
3.3.1 Optical Fiber	3-3
3.3.2 Optical Connectors	3-5
3.3.3 Materials	3-5
3.3.3.1 Toxicity	3-5
3.3.3.2 Corrosion Resistance	3-5
3.3.3.3 Dissimilar Metals	3-6
3.3.3.4 Fungus Resistance	3-6
3.3.3.5 Flammability	3-6
3.3.4 Safety	3-6
3.3.5 Mounting	3-7

3.3.5.1 Central Office Location	3-7
3.3.5.2 Outside Plant Location	3-9
4. Performance Criteria	4-1
4.1 Optical Criteria	4-3
4.1.1 Optical Bandwidth/Passband and Center Wavelength	4-3
4.1.2 Insertion Loss	4-4
4.1.3 Flatness	4-4
4.1.4 Wavelength Isolation or Optical Crosstalk	4-5
4.1.5 Reflectance	4-6
4.1.6 Polarization-Dependent Loss (PDL)	4-6
4.1.7 Other Optical Criteria for Dense WDM Systems	4-7
4.1.7.1 Center Wavelength Misalignment	4-7
4.1.7.2 Polarization Sensitivity of Center Wavelength and Optical Bandwidth	4-7
4.1.7.3 Temperature Sensitivity	4-8
4.2 Environmental Criteria	4-8
4.2.1 Operating Environment	4-9
4.2.2 Non-Operating Environment	4-10
4.2.3 Shock Criteria	4-10
4.2.3.1 Shipment from Manufacturer	4-10
4.2.3.2 Local Transportation	4-10
4.2.3.3 During Use	4-10
4.2.4 Vibration Test	4-10
4.2.5 Airborne Contaminants	4-11
4.2.6 Flex Test	4-11
4.2.7 Twist Test	4-12
4.2.8 Side Pull	4-12
4.2.9 Cable Retention	4-12
5. Performance Verification/Test Procedures	5-1
5.1 Optical Testing	5-1
5.1.1 Optical Passband/Bandwidth	5-2
5.1.2 Insertion Loss	5-3
5.1.3 Flatness	5-3
5.1.4 Wavelength Isolation or Optical Crosstalk	5-3
5.1.5 Reflectance	5-4
5.1.6 Polarization-Dependent Loss (PDL)	5-4
5.1.7 Other Optical Criteria for Dense WDM Systems	5-4
5.1.7.1 Center Wavelength Misalignment	5-4
5.1.7.2 Polarization Sensitivity of Center Wavelength and Optical Bandwidth	5-4
5.1.7.3 Temperature Sensitivity	5-4
5.2 Environmental Testing	5-4
5.2.1 Operating Environment	5-5
5.2.2 Non-Operating Environment	5-5
5.2.3 Shock Tests	5-5
5.2.3.1 Shipment from Manufacturer	5-5

- 5.2.3.2 Local Transportation 5-5
- 5.2.3.3 In Use 5-6
- 5.2.4 Vibration Test 5-6
- 5.2.5 Airborne Contaminants Test 5-6
- 5.2.6 Flex Test 5-6
- 5.2.7 Twist Test 5-6
- 5.2.8 Side Pull 5-6
- 5.2.9 Cable Retention 5-7
- 6. Reliability and Quality Assurance Program 6-1
 - 6.1 Reliability Assurance Requirements Philosophy 6-1
 - 6.2 Overview of Reliability Assurance 6-1
 - 6.3 Qualification Criteria 6-3
 - 6.3.1 Characterization 6-3
 - 6.3.2 Reliability Tests 6-4
 - 6.3.3 Failure Rate Prediction 6-8
 - 6.3.4 Optical Adhesives 6-11
 - 6.3.5 Quality Assurance and Lot Controls 6-11
 - 6.3.5.1 Visual Inspection 6-12
 - 6.3.5.2 Optical Testing 6-12
 - 6.3.5.3 Stress Screening 6-12
 - 6.3.6 Optical Adhesives 6-13
 - 6.3.7 Optical Connectors 6-13
 - 6.3.8 Optical Fiber 6-13
 - 6.4 Quality and Reliability Criteria 6-13
 - 6.4.1 Reliability Assurance 6-14
 - 6.4.2 Quality Technology Program 6-15
- Appendix A: References A-1
- Appendix B: Acronyms B-1
- Appendix C: Glossary C-1

List of Figures

Figure 2-1	Block diagram of a fiber optic filter	2-1
Figure 2-2	Forming a grating structure in an optical fiber	2-3
Figure 2-3	1480 nm pump filter in an EDFA	2-4
Figure 2-4	Pump power suppression using a longpass filter at the amplifier output	2-5
Figure 2-5	Fiber Bragg-grating filter for pump power reflection	2-5
Figure 2-6	Broadcast-and-select WDM star network	2-7
Figure 2-7	(a) Wavelength-routing WDM network and (b) associated wavelength assignment table	2-8
Figure 2-8	WADM using optical circulators	2-9
Figure 2-9	WADM using dielectric thin film bandpass filters	2-9
Figure 2-10	General Schematic: Non-Intrusive Testing of Optical Network . .	2-10
Figure 2-11	WDM/Filter Technique for Non-Intrusive Testing	2-11
Figure 2-12	Coupler/Filter Technique for Non-Intrusive Testing	2-11
Figure 3-1	Generic Frame Mountable Filter	3-7
Figure 3-2	Possible Filter Location in a Central Office	3-8
Figure 3-3	Example of a Filter Mounted in an OSP Closure	3-9
Figure 6-1	Elements of a Comprehensive Reliability Assurance Program . . .	6-3

List of Tables

Table 4-1	Summary of Fiber Optic Filter Performance Criteria and Test Sequence	4-1
Table 4-2	Optical Passband/Center wavelength Criteria	4-3
Table 4-3	Tensile Loads for Mechanical Tests	4-9
Table 4-4	Fiber Retention Loads	4-12
... Table 1	(R) Required Reliability Tests	6-4
Table 6-1	Test Matrix for Demonstrating Acceleration Factors [Relative Humidity as a Function of Temperature and Absolute Humidity]	6-7
... Table 2	(O) Sample Format for Reporting Failure Rate Predictions	6-10
... Table 3	(O) Sample Report Format for Reliability Test Status	6-11