

---

# Adhesive Certification

## Contents

## [Telcordia SR-4407-Documentation Information](#)

1. Introduction.....	1-1
2. Certification Assessment.....	2-1
2.1 Applicability.....	2-1
2.2 Procedures.....	2-1
2.2.1 Selection of Sample .....	2-1
2.2.2 Criteria Set .....	2-1
2.2.3 Use of Manufacturer's Data.....	2-1
2.2.4 Observation of Tests .....	2-2
2.2.5 Retesting.....	2-2
2.2.6 Results Documented in a Test Conformance Report .....	2-2
2.2.7 Recertification.....	2-2
2.3 Criteria Set .....	2-3
3. Certification Mark Support.....	3-1
3.1 Notification and Assessment of Product/Process Change .....	3-1
3.2 Spot Checking .....	3-1
4. Test Procedures .....	4-1
4.1 Adhesion Test.....	4-1
4.2 Flammability Test .....	4-1
4.3 Resistance to Soldering Test .....	4-1
4.4 Surface Insulation Resistance Test.....	4-1
4.4.1 Sample Coupon Preparation.....	4-1
4.4.2 Surface Insulation Resistance Test Procedure .....	4-1
4.5 Electromigration Test.....	4-2
4.5.1 Sample Coupon Preparation.....	4-2
4.5.2 Electromigration Test Procedure .....	4-2
4.6 Endurance Tests .....	4-2
4.6.1 85°C/85% RH Test.....	4-2
4.6.2 Temperature-Humidity Cycling Tests .....	4-2
4.7 Other Tests .....	4-2
4.7.1 Slump (Spread) Test.....	4-2
4.7.2 Glass Transition Temperature Test.....	4-3
References .....	References-1