

Table of Contents

1 Introduction

1.1 Scope and Purpose	1-2
1.2 Changes in the Document	1-2
1.3 Reasons for Reissues	1-2
1.3.1 Reasons for GR-1221-CORE, Issue 3	1-2
1.3.2 Reasons for GR-1221-CORE, Issue 2	1-3
1.3.3 Reasons for GR-1221-CORE, Issue 1	1-4
1.3.4 Future Additions/Changes	1-4
1.4 Related Telcordia Documents	1-4
1.5 Requirements Terminology	1-5
1.6 Requirement Labeling Conventions	1-6
1.6.1 Numbering of Requirement and Related Objects	1-6
1.6.2 Requirement, Conditional Requirement, and Objective Identification	1-6
1.7 Operating Environments	1-7
1.8 Other Terminology	1-7
1.8.1 Suppliers, Vendors, and Manufacturers	1-7
1.8.2 Quality Levels	1-7

2 Reliability Assurance – Overview and Philosophy

2.1 Overview of Reliability Assurance	2-1
2.2 Generic Requirements Philosophy	2-2

3 Basic Reliability Assurance Program Requirements

3.1 Vendor and Device Qualification	3-1
3.1.1 Specification and Control	3-2
3.1.2 Vendor Approval	3-3
3.1.3 General Criteria for Device Qualification	3-3
3.1.3.1 Qualification Tests	3-4
3.1.3.2 Device Codes That Fail Qualification	3-4
3.1.3.3 Qualification of Devices by Similarity and Bridge	3-5
3.1.3.4 Use of Nonconforming Devices for Qualification	3-5
3.1.3.5 Provisional Use of Devices	3-5
3.1.3.6 Low Volume Parts	3-6
3.1.3.7 Hermeticity	3-7
3.1.3.8 Solder Flux	3-7
3.1.3.9 Use of Vendor-Supplied Data	3-7
3.1.3.10 Treatment of Internally Manufactured Devices	3-8
3.1.4 Environment, Health, and Safety Considerations (Informational)	3-8
3.1.4.1 Environment Considerations	3-8
3.1.4.2 Health Considerations	3-8
3.1.4.3 Safety Considerations	3-9
3.1.5 Other General Information for Qualification	3-9
3.1.6 Requalification	3-11
3.2 Lot-to-Lot Quality and Reliability Controls	3-13
3.2.1 General Criteria for Lot Controls	3-13
3.2.1.1 Definition of a Lot	3-13

3.2.1.2	Purchase Specifications	3-14
3.2.1.3	Source Inspection/Incoming Inspection	3-14
3.2.1.4	Ship-to-Stock Programs	3-15
3.2.1.5	Test Plan	3-16
3.2.1.6	Test Equipment	3-16
3.2.1.7	Data Recording and Retention	3-16
3.2.1.8	Treatment of Defective Devices and Lots	3-17
3.2.1.9	Summary of Vendor History Data	3-17
3.2.1.10	Low Volume Parts	3-17
3.2.1.11	Use of Vendor-Supplied Data	3-17
3.2.1.12	Treatment of Internally Manufactured Devices	3-18
3.2.2	Other General Information for Lot-To-Lot Controls	3-18
3.3	Standardized Test Procedures	3-19
3.4	Feedback and Corrective Action	3-19
3.4.1	Incoming Inspection and Screening	3-20
3.4.2	System-Level Testing	3-21
3.4.3	Repair of Field Returns	3-21
3.4.4	Data Collection and Analysis	3-21
3.4.5	Unconfirmed Failures	3-22
3.4.6	Device Failure Analysis	3-22
3.5	Device Storage and Handling	3-22
3.5.1	Nonconforming Material	3-23
3.5.2	Material Review System	3-23
3.5.3	Stockroom Inventory Practices	3-23
3.5.3.1	First-In/First-Out (FIFO) Inventory Policy	3-23
3.5.3.2	Reworked Parts	3-23
3.5.4	Electrostatic Discharge (ESD)	3-24
3.6	Documentation and Test Data	3-24
3.6.1	Availability of Documentation	3-24
3.6.2	Availability of Other Information	3-25
3.7	Availability of Devices	3-26

4 Specific Reliability and Quality Criteria

4.1	Qualification of Passive Optical Devices	4-1
4.1.1	Characterization	4-1
4.1.2	Reliability Tests	4-3
4.2	Qualification of Integrated Passive Optical Module	4-8
4.3	Quality Assurance and Lot Controls	4-9
4.3.1	Visual Inspection	4-9
4.3.2	Optical Testing	4-10
4.3.3	Stress Screening	4-11
4.3.4	Optical Adhesives	4-12
4.3.5	Optical Fiber	4-12
4.4	Reliability and Quality of Optical Adhesives	4-12
4.4.1	Qualification and Requalification	4-13
4.4.2	Raw Material Storage	4-15
4.4.3	Lot-To-Lot Controls	4-15

5 Performance Criteria

5.1	Optical Requirements and Objectives	5-1
-----	---	-----

5.2 Optical Test Procedures	5-1
5.3 Optical Fiber and Optical Connectors	5-1

6 Reliability Test Procedures

6.1 Reliability Test Pass/Fail Criteria	6-1
6.2 Reliability Test Procedures	6-2
6.2.1 Mechanical Shock (Impact Test)	6-2
6.2.2 Vibration Test	6-3
6.2.3 Thermal Shock Test	6-4
6.2.4 High Temperature Storage Test (Dry Heat)	6-4
6.2.5 High Temperature Storage Test (Damp Heat)	6-5
6.2.6 Low Temperature Storage Test	6-6
6.2.7 Temperature Cycling Test	6-6
6.2.8 Cyclic Moisture Resistance Test	6-7
6.2.9 Residual Gas Analysis	6-7
6.2.10 ESD Threshold	6-7
6.2.11 High Power Testing	6-7
6.2.12 Airborne Contaminants Test	6-8
6.2.13 Water Immersion Test	6-8
6.2.14 Salt-Fog Test	6-8

Appendix A: Lot Tolerance Percentage Defective (LTPD) Table

Appendix B: Example Operational Shock and Vibration Proposal

B.1 Definitions	B-1
B.2 Test Conditions	B-1
B.3 Test Fixtures	B-2
B.4 Sample Size	B-3
B.5 Measurement Methodology	B-3
B.6 Acceptance Criteria	B-4

Appendix C: Reliability Calculation

C.1 Median Life	C-2
C.2 Design of Experiments to Generate Failure Mechanism Equations	C-3
C.3 Acceleration Factor Models	C-4
C.4 CDF in Accelerated Test Conditions	C-5
C.5 CDF at Field Operating Conditions	C-8
C.6 Estimating Onset of Wearout	C-9
C.7 Performing Risk Assessment on Sub-Assemblies	C-9
C.8 Determine Minimum Stress Level Criteria	C-10
C.9 Generate Cumulative Failure Distribution	C-10

Appendix D: References

D.1 Telcordia References	D-1
D.2 Non-Telcordia References	D-2
D.3 Internet References	D-3
D.4 Telcordia Reference Notes	D-4
D.4.1 Contact Telcordia	D-4
D.4.2 Order Documents Online From the Telcordia Information SuperStore	D-4

D.4.3 Telcordia Web Sites for Generic Requirements Information D-5
D.4.4 Telcordia Licensing Agreements D-5

Appendix E: Glossary

E.1 Acronyms E-1
E.2 Terms E-3

Requirement-Object Index

List of Figures

Figure 2-1	Elements of a Comprehensive Reliability Assurance Program	2-2
Figure B-1	Output Power Variation	B-1
Figure C-1	CDF of the Accelerated Test Data	C-7
Figure C-2	CDFs at Accelerated Damp Heat and Field Conditions	C-8
Figure C-3	Sample Data Weibull Plot	C-11

List of Tables

Table 1-1	Definition of Quality Levels	1-8
Table 3-1	Requirements for Provisional Use of Devices in Qualification	3-6
Table 3-2	Sample Format for Reporting Failure Rate Predictions	3-10
Table 3-3	Sample Report Format for Reliability Test Status	3-11
Table 4-1	Typical Characterization Tests for Branching Components	4-2
Table 4-2	Required Reliability Tests	4-5
Table 4-3	Test Matrix for Demonstrating Acceleration Factors	4-7
Table 4-4	Typical Optical Parameters for Branching Components	4-10
Table A-1	LTPD Sampling Plan	A-1
Table B-1	Operational Shock and Vibration Test Conditions	B-2
Table B-2	Operational Shock and Vibration Measurement Requirements	B-3
Table B-3	Operational Shock and Vibration Acceptance Criteria	B-4
Table C-1	Most Frequently Used CDF	C-2
Table C-2	Minimum Suite of Tests Required to Estimate the Coefficient Constants of Each Equation	C-3
Table C-3	Minimum Suite of Tests Required to Estimate the Coefficient	C-6
Table C-4	Onset of Wearout	C-9
Table C-5	Data Example	C-10