

Contents

Preface	ix
1 Introduction	
1.1 Purpose and Scope	1-1
2 Station Protector Limiting Voltages	
3 Metallic Surges – Lightning	
4 Longitudinal Surges - Lightning	
5 Power-Caused Voltages and Currents	
5.1 Long-Term Induction on Telephone Conductors	5-1
5.2 Power Line Fault Induction on Telephone Conductors	5-6
5.3 Power Contact to Telephone Conductors	5-7
6 Radio Frequency Voltages	
6.1 General	6-1
6.2 Factors Influencing RF Coupling	6-1
6.3 Factors Influencing Interference from RF Voltages	6-2
6.4 Characteristics of RF Voltages at the NI	6-2
Appendix A: References	
Note	A-2
To Contact Telcordia Customer Service or to Order Documents	A-2
To Order Documents From Within Telcordia (Employees Only)	A-2

List of Figures

Figure 2-1	Definition of Double-Exponential Impulse Waveform of Duration A/B Seconds	2-2
Figure 3-1	Distribution of First-Stroke Events Per Thunderstorm Day Exceeding Voltage Thresholds With Protector Removed	3-3
Figure 3-2	Distribution of First-Stroke Events Per Thunderstorm Day Exceeding Short-Circuit Current Thresholds	3-5
Figure 5-1	Maximum and Average Noise Voltage To Ground at the NI in a 24-Hour Period	5-2
Figure 5-2	C-Message Weighted Noise Voltage to Ground for Urban, Suburban, Rural, and All RBOC Loop Populations as Measured at the NI . . .	5-3
Figure 5-3	3-kHz Flat Weighted Noise Voltage to Ground for Urban, Suburban, Rural, and All RBOC Loop Populations as Measured at the NI . . .	5-4
Figure 5-4	Distributions of Normalized (to 3-kHz Flat) Spectral Components of Induced Longitudinal Voltage as Measured at the NI	5-5
Figure 5-5	Longitudinal Current for Urban, Suburban, Rural, and All RBOC Loop Populations as Measured at the NI	5-6

List of Tables

Table 3-1	Parameters of Sites at Which Lightning Disturbances to the Telephone Loop Were Studied	3-2
Table 6-1	Summary of Conducted RF Voltage Measurements (Highest Levels Measured)	6-3
Table 6-2	Summary of Conducted RF Voltage Measurements (Lowest Levels Measured at Locations Reporting RFI Problems)	6-4