

Generic Requirements for Portable Wavelength Division Multiplexer Analyzers

Contents

Preface	Preface-1
1. Introduction.....	1-1
1.1 Purpose and Scope of Document	1-1
1.2 Organization	1-1
1.3 Requirements Terminology.....	1-1
1.4 Requirement Labeling Conventions.....	1-2
1.4.1 Numbering of Requirement and Related Objects	1-2
1.4.2 Requirement, Conditional Requirement, and Objective Object Identification	1-3
1.5 Reason for Revision 1 to be Issued	1-3
1.6 Target Audience	1-3
2. General Information.....	2-1
2.1 Product Definition	2-1
2.1.1 Principles of Operation	2-1
2.1.2 Operational Summary of Multi-Wavelength Test Sets.....	2-1
2.1.2.1 Optical Spectrum Analyzers	2-2
2.1.2.2 Multi-Wavelength Meters.....	2-4
2.2 Applications and Uses.....	2-4
2.2.1 Key WDM System Components Which Require Testing	2-5
2.2.1.1 Source	2-5
2.2.1.2 Multiplexer/demultiplexer	2-5
2.2.1.3 Erbium Doped Fiber Amplifier	2-5
2.2.2 Tests Which May Be Performed	2-6
2.2.2.1 Optical Power/Loss.....	2-6
2.2.2.2 Frequency Stability or Drift.....	2-7
2.2.2.3 Optical Crosstalk	2-7
2.2.2.4 Polarization Dependent Loss	2-7
2.2.2.5 Tests Unique to the Demultiplexer	2-7
2.3 Operating Environment.....	2-8
3. General Requirements and Objectives.....	3-1
3.1 Display and Control Features.....	3-1
3.2 Operational Features	3-1
3.3 Unit Powering Features.....	3-2
3.4 Input/Output Port Features	3-3
3.5 Mechanical Design.....	3-3

3.6	Maintenance	3-3
3.7	Product Information	3-4
3.7.1	Documentation	3-4
3.7.2	Performance Specification Sheet	3-4
3.8	Product and Packaging Markings.....	3-6
3.8.1	Product Markings	3-6
3.8.2	Packaging Markings.....	3-6
3.9	Laser Protection	3-7
4.	Specific Requirements and Objectives	4-1
4.1	Operational Criteria.....	4-1
4.2	Mechanical Design Criteria.....	4-2
4.2.1	Shock Tests	4-2
4.2.1.1	Shipment from Manufacturer	4-2
4.2.1.2	Local Transportation.....	4-3
4.2.1.3	During Use.....	4-3
4.2.2	Vibration Test	4-3
4.3	Power Criteria	4-3
4.4	Environmental Criteria.....	4-3
4.4.1	Non-Operating Environment.....	4-3
4.4.2	Operating Environment.....	4-4
4.4.3	Dust Resistance	4-4
4.5	Electromagnetic Interference and Electrostatic Discharge	4-4
4.5.1	Electromagnetic Interference	4-4
4.5.2	Electrostatic Discharge	4-4
4.6	Safety Criteria	4-5
5.	Performance Verification and Test Procedures	5-1
5.1	Operation.....	5-1
5.2	Mechanical Design.....	5-2
5.2.1	Shock Tests	5-3
5.2.1.1	Shipment from Manufacturer	5-3
5.2.1.2	Local Transportation.....	5-3
5.2.1.3	During Use.....	5-4
5.2.2	Vibration Test	5-4
5.3	Power.....	5-4
5.4	Environment.....	5-4
5.4.1	Non-Operating Environment.....	5-5
5.4.2	Operating Environment.....	5-5
5.5	Electromagnetic Interference and Electrostatic Discharge	5-5
5.5.1	Electromagnetic Interference	5-5
5.5.2	Electrostatic Discharge	5-5
5.6	Protection	5-6
5.6.1	Grounding	5-6
5.6.2	Leakage Current.....	5-6

5.6.3 Hot Surfaces.....	5-6
References	References-1
Glossary	Glossary-1

List of Figures

Figure 2-1.	Fabry-Perot Interferometer	2-2
Figure 2-2.	Michelson Interferometer	2-3
Figure 2-3.	Single Diffraction Grating Optical Spectrum Analyzer	2-3
Figure 5-1.	General Operations Test Setup for WDM Analyzer	5-2

List of Tables

Table 3-1.	Performance Specification Sheet: WDMA.....	3-4
Table 5-1.	Drop Test Heights.....	5-3
Table 5-2.	Vibration Test Parameters	5-4
Table 5-3.	Environmental Extreme Requirements.....	5-4