

Contents

1 Introduction

1.1 Purpose and Scope	1-1
1.2 Organization	1-1
1.3 Reasons for GR-771-CORE Re-Issues	1-2
1.3.1 Reasons for GR-771-CORE, Issue 2	1-2
1.3.2 Reasons for GR-771-CORE, Issue 1	1-4
1.4 Requirements Terminology	1-5
1.5 Requirement Labeling Conventions	1-6
1.5.1 Numbering of Requirement and Related Objects	1-6
1.5.2 Requirement, Conditional Requirement, and Objective Identification	1-6

2 General Information

2.1 Product Description	2-1
2.2 Deployment Environments	2-4
2.2.1 Outside Plant (OSP)	2-4
2.2.2 Inside Plant	2-5
2.3 Installation and Operating Environment	2-5
2.4 Test Sequence	2-6
2.5 Test Environmental Criteria	2-6
2.5.1 Ambient Laboratory Conditions	2-6
2.5.2 Environmental Tests	2-6
2.6 Safety Precautions	2-7
2.7 Glossary of Terms	2-7

3 General Requirements and Objectives

3.1 Documentation	3-1
3.1.1 Practices	3-1
3.1.2 Workcenter Information Package	3-1
3.2 Markings, Packaging, and Shipping	3-2
3.2.1 Identification	3-2
3.2.2 Shipping Container and Packaging Arrangement	3-2
3.2.3 Package Label	3-2
3.2.4 Package Quality	3-3
3.2.5 Consumable Materials	3-3
3.3 Initial Product Qualification and Periodic Requalification	3-3
3.4 Quality	3-4
3.5 Product Change Notices (PCNs)	3-4

4 Splice Closure Features and Functions

4.1 Common Closure Requirements	4-1
4.1.1 Cable Compatibility	4-1
4.1.2 Cable Entrance Capacity	4-1

4.1.3	Cable Termination System	4-2
4.1.4	Bonding and Grounding Hardware	4-2
4.1.5	Closure Mounting Hardware	4-2
4.1.6	Fiber and Splice Organization	4-3
4.1.7	Fiber and Splice Storage Capacity	4-4
4.1.8	Fiber and Splice Protection	4-5
4.1.9	Maintenance	4-5
4.1.10	Components	4-6
4.1.11	Installation Size and Weight	4-6
4.1.12	Safety	4-7
4.1.13	Restriction of Hazardous Substances (RoHS) Compliance	4-7
4.1.14	Security	4-7
4.1.15	Tools	4-7
4.2	Taut Sheath Closures (TSCs)	4-8
4.2.1	Closure Configuration	4-8
4.2.2	Cable Termination	4-8
4.2.3	Cable Capacity	4-8
4.2.4	Cable Sheath Opening	4-8
4.2.5	Fiber Splicing	4-9
4.2.6	Fiber and Splice Storage	4-9
4.3	Free-Breathing Closures (FBCs)	4-10
4.3.1	Drainage for Condensate	4-10
4.3.2	Insect Resistance	4-10
4.4	Environmentally Sealed Closures (ESCs)	4-10
4.4.1	Air Valve	4-10
4.5	Pre-Terminated Closures (PTCs)	4-11
4.5.1	Closure Dimensions	4-11
4.6	Hybrid Fiber Closures (HFCs)	4-12
4.7	Pedestal Closures	4-12
4.8	Multiple Dwelling Unit (MDU)	4-12

5 Performance Requirements and Objectives

5.1	General	5-1
5.1.1	Conformance Test Program Structure	5-1
5.1.2	Test Schedule	5-2
5.1.3	Sample Preparation	5-5
5.1.3.1	Sample Size	5-6
5.1.4	Test Conditions/Temperatures	5-6
5.1.4.1	Installation Tests	5-6
5.1.4.2	Operating Tests	5-7
5.1.4.3	Soak Times	5-7
5.1.5	Mechanical Stresses	5-8
5.1.6	Optical Measurements	5-9
5.1.7	Re-Testing	5-11
5.1.7.1	Re-Testing Matrix	5-11

5.2	Electrical Criteria	5-12
5.2.1	Bond Clamp Retention	5-12
5.2.1.1	Bond Clamp Retention Test Method	5-12
5.2.2	Corrosion Resistance	5-12
5.2.3	AC Fault Test	5-12
5.2.3.1	AC Fault Test Method	5-13
5.3	Mechanical Criteria	5-16
5.3.1	Cable Clamping	5-16
5.3.1.1	Cable Clamping Test Method	5-17
5.3.2	Sheath Retention	5-17
5.3.2.1	Sheath Retention — Test Method	5-18
5.3.3	Cable Flexing	5-19
5.3.3.1	Cable Flexing Test Method	5-20
5.3.4	Cable Torsion	5-22
5.3.4.1	Cable Torsion Test Method	5-23
5.3.5	Vertical Drop	5-24
5.3.5.1	Vertical Drop Test Method	5-24
5.3.6	Compression	5-25
5.3.6.1	Compression Test Method	5-25
5.3.7	Impact	5-28
5.3.7.1	Impact Test Method	5-29
5.3.8	Transportation Vibration	5-32
5.3.8.1	Transportation Vibration Test Method	5-32
5.3.9	Environmental Vibration Resistance	5-33
5.3.9.1	Environmental Vibration Test Method	5-34
5.3.10	Central Member (CM) Protrusion	5-35
5.3.10.1	Central Member Protrusion Test Method	5-35
5.4	Environmental Criteria	5-39
5.4.1	Accelerated Thermal Aging	5-39
5.4.1.1	Thermal Aging Test Method	5-40
5.4.2	Assembly	5-40
5.4.2.1	Assembly Test Method	5-41
5.4.3	Temperature and Humidity	5-41
5.4.3.1	Temperature and Humidity Test Method	5-41
5.4.4	Freeze/Thaw	5-43
5.4.4.1	Freeze/Thaw Test Method	5-44
5.4.5	Weathertightness	5-51
5.4.5.1	Weathertightness (Dust) Test Method	5-51
5.4.6	Water Resistance	5-52
5.4.6.1	Water Resistance Test Procedures	5-53
5.5	Materials Criteria	5-55
5.5.1	Metallic	5-55
5.5.2	Non-Metallic	5-55
5.5.3	Corrosion Resistance	5-55
5.5.3.1	Corrosion Resistance Test Method	5-56
5.5.4	Chemical Resistance	5-57
5.5.4.1	Material Degradation	5-58

5.5.4.2 Chemical Immersion	5-60
5.5.5 Ultraviolet Resistance	5-62
5.5.5.1 UV Resistance Test Method	5-63
5.5.6 Fungus Resistance	5-63
5.5.6.1 Fungus Resistance Test Procedure	5-64
5.6 Conditional Requirements	5-64
5.6.1 Firearms Resistance	5-64
5.6.1.1 Firearms Resistance Test Method	5-65
5.6.2 Rodent Resistance	5-66
5.6.3 Steam Resistance	5-67
5.6.3.1 Steam Resistance Test Method	5-67
5.6.4 Fire Resistance	5-67
5.6.4.1 Fire Resistance Test Method	5-68

6 Performance Verification

Appendix A: Optical Measurements

A.1 Apparatus	A-1
A.2 Transmission Measurement Facility	A-1
A.3 Backscatter Measurement Facility (OTDR)	A-2

Appendix B: Observational Standard

Appendix C: References

C.1 Telcordia Documents	C-1
C.2 Additional Reference Material	C-2

Appendix D: Acronyms

Requirement-Object Index (ROI)

List of Figures

Figure 5-1	Splicing Assignment for Ribbon Fiber	5-9
Figure 5-2	AC Fault Test	5-15
Figure 5-3	Sheath Retention Test	5-19
Figure 5-4	Cable Flex Test	5-22
Figure 5-5	Cable Torsion Test	5-23
Figure 5-6	Typical Target Areas for Compression Test	5-27
Figure 5-7	Compression Test	5-28
Figure 5-8	Impact Test Configuration — Wall- or Pole-Mounted Products	5-31
Figure 5-9	Impact Test Configuration — Aerial-Mounted Products	5-32
Figure 5-10	Transportation Vibration Environment	5-33
Figure 5-11	Central Member Test Fixture	5-35
Figure 5-12	Central Member Protrusion Test	5-36
Figure 5-13	Jacket Clamped with Central Member Free to Move	5-37
Figure 5-14	Central Member Moves Out of the Cable End as the Jacket Shrinks	5-37
Figure 5-15	Central Member Clamped with Jacket Free to Move	5-38
Figure 5-16	Jacket Shrinks Back Relative to the Central Member	5-38
Figure 5-17	Force Arising from Jacket Shrinkage in a Clamped Situation	5-39
Figure 5-18	Temperature Cycle	5-42
Figure 5-19	Sectional Side View of Freeze/Thaw Test Setup #1	5-45
Figure 5-20	Top View of Freeze/Thaw Test Setup #1	5-46
Figure 5-21	Section Side View of Freeze/Thaw Test Setup #2	5-47
Figure 5-22	Location of Thermocouples	5-48
Figure 5-23	Three-Point Test Fixture	5-60
Figure 5-24	Firearms Resistance Test	5-66
Figure 5-25	Vertical Test Rack	5-71
Figure 5-26	Burner Arrangement — Vertical Test	5-72
Figure 5-27	Horizontal Test Equipment	5-75
Figure 5-28	Sample Placement — Horizontal Test	5-76
Figure A-1	Transmission Measurement Test Facility	A-2
Figure A-2	OTDR Measurement Test Facility	A-2
Figure B-1	Telcordia Observational Standard for Evaluating Dust Accumulation	B-1

List of Tables

Table 2-1	Closure Types vs. Applications	2-2
Table 4-1	Estimated Minimum Splice Capacity of Closure	4-4
Table 5-1	Performance Test Sequence	5-3
Table 5-2	Installation Test Temperatures	5-7
Table 5-3	Operating Test Temperatures	5-7
Table 5-4	Sheath Retention Criteria Levels	5-18
Table 5-5	Impact Criteria Levels	5-29
Table 5-6	Transportation Vibration Test Severity	5-33
Table 5-7	Freeze/Thaw Criteria	5-43
Table 5-8	Weathertightness Criteria	5-51
Table 5-9	Water-Resistance Criteria Levels	5-52
Table 5-10	Corrosion Resistance Criteria Levels	5-56
Table 5-11	Immersion Test Fluids	5-62
Table 5-12	Ultraviolet Resistance Sources	5-63