

Table of Contents

1 Introduction

1.1 Reason for GR-78-CORE, Issue 2	1-1
1.2 Organization	1-1
1.3 Requirements Terminology	1-2
1.4 Requirement Labeling Conventions	1-3
1.4.1 Numbering of Requirement and Related Objects	1-3
1.4.2 Requirement, Conditional Requirement, and Objective Identification	1-3
1.5 General Criteria	1-4

2 Requirements for All Products

2.1 General	2-1
2.2 Electrical and Mechanical Integrity	2-2
2.3 Administration of Requirements	2-3

3 Materials and Finishes Requirements

3.1 General	3-1
3.2 Materials	3-1
3.2.1 Fire Resistance Requirements	3-1
3.2.2 Fire Risk Analysis	3-2
3.2.3 Fluxes	3-2
3.2.4 Silver	3-2
3.2.5 Silicones	3-3
3.3 Finishes	3-3

4 Separable Connector Requirements

4.1 General	4-1
4.1.1 Connector Selection Considerations	4-1
4.1.2 Lubrication	4-3
4.1.3 Connector Durability	4-5
4.2 Two-Part and PWB Edge Card Connectors	4-7
4.2.1 Design	4-7
4.2.2 Polarization	4-7
4.2.3 Insertion and Removal Forces	4-8
4.2.4 Usage	4-8
4.3 Insulation Displacement Connectors (IDCs)	4-8

5 Wire and Cable Requirements

5.1 Metallic Wire and Cable	5-1
5.1.1 Outside Plant Cable	5-1
5.1.2 Outside Plant Wire (OPW)	5-2
5.1.3 Inside Wire and Cable (Customer Premises and COs)	5-2
5.1.4 Materials	5-3
5.1.5 Performance	5-4
5.1.6 Wire and Cable Preparation for Equipment Assemblies	5-5
5.1.7 Cable and Wire Termination	5-5

5.2 Optical Fiber and Optical Fiber Cables 5-7

6 Printed Wiring Board (PWB) Requirements

6.1 General 6-1

6.1.1 Materials 6-1

6.1.1.1 Laminates 6-1

6.1.1.2 Solder Mask 6-2

6.1.1.3 Legend and Marking Inks 6-2

6.1.1.4 Repair Polymers 6-2

6.1.1.5 Conductor Materials and Finishes 6-2

6.1.2 Design 6-3

6.1.2.1 Dimensioning 6-3

6.1.2.2 PWB Contact Fingers 6-3

6.1.2.3 Interlayer Connections 6-4

6.1.2.4 Warpage 6-4

6.1.2.5 Protective Coatings 6-5

6.1.2.6 Resistance to Airborne Contaminants 6-5

6.1.3 Manufacturing 6-5

6.1.3.1 General 6-5

6.1.3.2 Conductor Widths and Spacings 6-6

6.1.3.3 Conductor Adhesion 6-6

6.1.3.4 Plated Through Holes (PTHs) 6-7

6.1.3.5 Conductor Finishes 6-8

6.1.3.6 Solderability 6-9

6.1.3.7 Solder Masks 6-9

6.1.3.8 PWB Contact Fingers 6-11

6.1.3.9 Insulation Resistance Testing 6-12

6.1.3.10 Solvent Extract Conductivity Testing 6-13

6.1.3.11 Mechanical Damage 6-14

6.1.3.12 Laminate and Processing Defects 6-15

6.1.3.13 Electrical 6-16

6.1.3.14 Repairs 6-16

6.1.3.15 Modifications — General 6-17

6.1.3.16 Modifications — Subtractive 6-18

6.1.3.17 Modifications — Additive 6-19

6.2 Multilayer PWBs — General Requirements 6-21

6.2.1 Design 6-21

6.2.1.1 Dimensioning 6-21

6.2.1.2 Interlayer Connections 6-22

6.2.1.3 Construction 6-22

6.2.2 Manufacturing 6-24

6.2.2.1 Conductor Widths and Spacings 6-24

6.2.2.2 Plated Through Holes (PTHs) 6-24

6.2.2.3 Insulation Resistance Testing — Inner Signal Layers 6-25

6.2.2.4 Insulation Resistance Testing — Interlayer 6-26

6.2.2.5 SEC Testing 6-26

6.2.2.6 Laminate and Processing Defects 6-26

6.2.2.7 Electrical Requirements 6-27

6.2.2.8 Repairs — Inner Layers Before Lamination 6-27

6.2.2.9 Repairs — Finished Multilayer PWBs 6-28



6.2.2.10	Modifications — Inner Layers Before Lamination	6–28
6.2.2.11	Modifications — Completed Multilayer PWBs	6–28
6.3	PWBs for Surface Mounting	6–29
6.3.1	General Requirements	6–29
6.3.1.1	Materials — Laminates	6–29
6.3.1.2	Materials — Solder Masks	6–29
6.3.1.3	Design — Component Mounting Pads	6–30
6.3.1.4	Design — Solder Masks	6–30
6.3.1.5	PWBs for Adhesive and Wavesolder Soldering Processes — Conductor Finish	6–30
6.3.1.6	PWBs for Adhesive and Wavesolder Soldering Processes — Component Mounting Pads	6–31
6.3.1.7	PWBs for Reflow Surface-Mount Soldering Processes — Conductor Finish	6–31
6.3.1.8	PWBs for Reflow Surface-Mount Soldering Processes — Component Mounting Pads	6–32
6.4	PWBs for Backpanels	6–33
6.4.1	Design	6–33
6.4.1.1	Dimensioning	6–33
6.4.1.2	Method of Manufacture	6–33
6.4.2	Manufacturing	6–33
6.4.2.1	Drilling	6–33
6.4.2.2	Plated Through Holes (PTHs)	6–34
6.5	Encapsulated Discrete Wire (EDW) Interconnection Boards	6–34

7 Printed Wiring Board (PWB) Assembly Requirements

7.1	General	7–1
7.1.1	Materials	7–1
7.1.1.1	Conformal Coatings	7–1
7.1.1.2	Fluxes	7–1
7.1.1.3	Solders and Solder Pastes	7–1
7.1.2	Assembly Design	7–2
7.1.2.1	General	7–2
7.1.2.2	Components	7–3
7.1.2.3	Layout — General	7–5
7.1.2.4	Layout — Thermal Considerations	7–5
7.1.2.5	Layout — Clearances	7–6
7.1.2.6	Layout — Lead Forms	7–7
7.1.2.7	Separable Connections	7–7
7.1.2.8	Conformal Coatings	7–7
7.1.3	Manufacturing	7–8
7.1.3.1	General	7–8
7.1.3.2	Clearances	7–10
7.1.3.3	Solderability	7–10
7.1.3.4	Soldering	7–10
7.1.3.5	Bow and Twist	7–11
7.1.3.6	Solder Masks	7–12
7.1.3.7	Conformal Coatings	7–12
7.1.3.8	Insulation Resistance Testing	7–13
7.1.3.9	SEC Testing	7–13

- 7.1.3.10 Lubrication 7-14
- 7.1.3.11 Mechanical Damage and Defects 7-14
- 7.1.3.12 Repair of PWB Assemblies — General 7-14
- 7.1.3.13 Repair of PWB Assemblies — Component Removal and Replacement 7-15
- 7.1.3.14 Repair of PWB Assemblies — PWB Repairs 7-16
- 7.1.3.15 Modifications to PWB Assemblies — General 7-16
- 7.1.3.16 Modifications to PWB Assemblies — Wiring Design 7-16
- 7.1.3.17 Modifications to PWB Assemblies — Wire Routing 7-17
- 7.1.3.18 Modifications to PWB Assemblies — Wire Preparation 7-18
- 7.1.3.19 Modifications to PWB Assemblies — Soldering of Modification Wires 7-18
- 7.1.3.20 Modifications to PWB Assemblies — Securing of Modification Wires 7-19
- 7.1.3.21 Modifications to PWB Assemblies — PWB Modifications 7-20
- 7.1.3.22 Modifications to PWB Assemblies — Components 7-20
- 7.2 PWB Assemblies — Through-Hole Mounted Components 7-21
 - 7.2.1 Assembly Design 7-21
 - 7.2.2 Manufacturing 7-21
 - 7.2.2.1 Soldering — PTH Solder Joints 7-21
 - 7.2.2.2 Soldering — Non-PTH Solder Joints 7-23
 - 7.2.2.3 Compliant Pin 7-23
- 7.3 PWB Assemblies — Surface Mounted Components (SMCs) 7-23
 - 7.3.1 Materials 7-23
 - 7.3.1.1 Solder Pastes — Incoming Material Controls 7-23
 - 7.3.1.2 Solder Pastes — In-Process Controls 7-24
 - 7.3.1.3 Solder Masks 7-25
 - 7.3.1.4 Adhesives 7-25
 - 7.3.2 Assembly Design 7-26
 - 7.3.2.1 General 7-26
 - 7.3.2.2 Components 7-26
 - 7.3.2.3 Thermal Considerations 7-27
 - 7.3.2.4 Lead Forms 7-27
 - 7.3.2.5 Termination Metallizations 7-27
 - 7.3.3 Reliability 7-27
 - 7.3.4 Manufacturing 7-28
 - 7.3.4.1 Soldering — General 7-28
 - 7.3.4.2 Soldering — Reflow Processes 7-28
 - 7.3.4.3 Soldering — Wavesoldering Processes 7-29
 - 7.3.4.4 Bow and Twist 7-29
 - 7.3.4.5 Electrical Requirements 7-30
 - 7.3.4.6 Repairs 7-30
 - 7.3.4.7 Modifications 7-30
 - 7.3.4.8 Ball Grid Array (BGA) Assembly 7-30
- 7.4 Backpanel PWB Assemblies 7-32
 - 7.4.1 Assembly Design 7-32
 - 7.4.1.1 Terminals/Pins 7-32
 - 7.4.1.2 Dimensioning 7-32
 - 7.4.2 Manufacturing 7-32
 - 7.4.2.1 Dimensions 7-32



7.4.2.2 Electrical Requirements	7-33
7.4.2.3 Plated-Through Hole (PTH) Deformation/Damage	7-33

8 Equipment Sub-Assembly and Assembly Requirements

8.1 General	8-1
8.1.1 Materials, Piece-Parts, and Sub-Assemblies	8-1
8.1.2 Sub-Assemblies and Assemblies	8-1
8.1.3 Design	8-1
8.2 Manufacturing	8-4
8.2.1 Connections	8-4
8.2.1.1 General	8-4
8.2.1.2 Soldered Connections	8-4
8.2.1.3 Solderless Wrapped Connections	8-5
8.2.2 Wiring and Cabling	8-7
8.3 Equipment Modifications	8-7
8.3.1 General	8-7
8.3.2 Modification Wiring	8-7
8.4 Performance	8-8
8.4.1 General	8-8
8.4.2 Operation Under Environmental Extremes	8-8

9 Electrostatic Discharge (ESD)

9.1 General	9-1
9.2 Susceptibility	9-1
9.3 ESD Resistance	9-1
9.4 Circuit Pack ESD Test Methods and Requirements	9-2
9.4.1 Scope and Purpose	9-2
9.4.2 ESD Considerations	9-2
9.4.2.1 General	9-2
9.4.2.2 Susceptibility	9-2
9.4.2.3 Performance Criteria	9-2
9.4.2.4 Documentation Specifications	9-2
9.4.3 Test Preparation	9-3
9.4.4 Safety	9-3
9.4.5 Experimental ESD Failure Threshold Measurement	9-4
9.4.5.1 Required Test Method	9-4
9.4.5.2 Equipment Required	9-4
9.4.5.3 Waveform Verification Procedure	9-6
9.4.5.4 Circuit Pack Testing Procedure	9-6
9.4.5.5 Circuit Pack Selection	9-7
9.4.6 Documentation of Test Result Definitions and Categories	9-7
9.5 ESD Labeling Requirements	9-8
9.5.1 ESD Susceptibility Symbol	9-8
9.5.1.1 Packaging	9-8
9.5.1.2 Equipment	9-8
9.5.2 ESD Protective Symbol	9-8

10 Product Identification and Markings Requirements

11 Package Requirements

11.1 General 11-1
11.2 Shipping of Assemblies 11-2

12 Repair and Modification of Customer Return Units

12.1 General 12-1
12.2 Marking 12-2
12.3 Repairs 12-2

13 Qualification Test Procedures

13.1 Corrosiveness of Soldering Fluxes 13-1
 13.1.1 Preparation of Fluxes for Testing 13-1
 13.1.2 Test Patterns for SIR and Electromigration Resistance Testing 13-2
 13.1.2.1 Test Pattern Preparation — Liquid Fluxes 13-3
 13.1.2.2 Test Pattern Preparation — Solder Pastes 13-4
 13.1.2.3 Test Pattern Preparation — Cored Solder Wire 13-5
 13.1.3 Surface Insulation Resistance (SIR) Test 13-5
 13.1.3.1 Equipment Required 13-5
 13.1.3.2 Test Procedure 13-6
 13.1.4 Electromigration Resistance Test 13-7
 13.1.4.1 Equipment Required 13-7
 13.1.4.2 Test Procedure 13-7
 13.1.4.3 Data Handling 13-8
 13.1.4.4 Visual Examination 13-9
 13.2 Polymeric Coatings and Adhesive Materials 13-9
 13.2.1 General 13-9
 13.2.2 Visual 13-10
 13.2.3 Adhesion 13-10
 13.2.4 Corrosion of Copper 13-11
 13.2.5 Test Patterns for Surface Insulation Resistance and Electromigration
 Testing 13-11
 13.2.5.1 Test Pattern Preparation 13-12
 13.2.6 Surface Insulation Resistance (SIR) Test 13-12
 13.2.6.1 Equipment Required 13-12
 13.2.6.2 Test Procedure 13-12
 13.2.6.3 Data Handling 13-13
 13.2.7 Testing for Resistance to Electromigration 13-14
 13.2.7.1 Equipment Required 13-14
 13.2.7.2 Test Procedure 13-14
 13.2.7.3 Data Handling 13-15
 13.2.7.4 Visual Examination 13-15
 13.2.8 Pre-Production Testing 13-16
 13.3 Separable Connector and Socketed Component Lubricant Qualification . . 13-16
 13.3.1 Lubricants for Gold-to-Gold or Similar Noble Metallizations 13-16
 13.3.2 Lubricants for Tin-to-Tin and Solder-to-Solder Separable
 Connections 13-17
 13.4 Qualification of Additive Circuitry for Bare PWB Modifications 13-19

14 Tests and Methods

14.1	General	14-1
14.2	Metal Finishes	14-1
14.2.1	Noble Metal Contact Finishes	14-1
14.2.2	Noble Metal Porosity Testing	14-1
14.2.2.1	Electrographic Testing — Paper	14-1
14.2.2.2	Electrographic Tests — Gel	14-2
14.2.2.3	Corrosive Gas Tests — Nitric Acid Vapor	14-2
14.2.2.4	Finish Adherence	14-2
14.3	PWBs	14-3
14.3.1	Preparation of Cross-Sections	14-3
14.3.2	Thermal Shock Testing of Plated Through Holes (PTHs)	14-3
14.4	Insulation Resistance Testing	14-3
14.4.1	Equipment Required	14-3
14.4.2	Insulation Resistance Test Patterns	14-3
14.4.3	Terminating Test Patterns	14-5
14.4.4	Test Procedure	14-5
14.4.5	Data Handling	14-6
14.4.6	Insulation Resistance Requirements	14-7
14.5	Solvent Extract Conductivity Testing	14-7
14.5.1	Equipment and Reagents Required	14-7
14.5.1.1	Equipment	14-7
14.5.1.2	Reagents	14-8
14.5.2	Calibration Procedure	14-8
14.5.2.1	Determination of Test Duration	14-8
14.5.2.2	Determination of Contamination Threshold	14-9
14.5.3	Testing of Production PWBs and Assemblies	14-9

Appendix A: References

Appendix B: Acronyms and Glossary

B.1	Acronyms	B-1
B.2	Glossary	B-3

Appendix C: Deleted Requirements

Requirement-Object Index