
Table of Contents

1. Introduction	1-1
1.1 Document Description.....	1-1
1.2 Summary of Significant Changes to TA	1-1
1.3 Analysis Criteria	1-1
1.4 Technical Feature/Function Analysis.....	1-2
1.5 Quality and Reliability Analysis.....	1-2
1.6 Organization	1-4
2. General Information.....	2-1
2.1 Product Definition.....	2-1
2.1.1 Principles of Operation.....	2-1
2.1.2 Performance	2-1
2.1.3 Data Output and Controls	2-2
2.1.4 Optical Power Meter Components	2-2
2.2 Applications and Uses.....	2-2
2.3 Operating Environment.....	2-3
2.4 Fiber Optic System Considerations	2-3
3. General Requirements.....	3-1
3.1 Displays and Control Features.....	3-1
3.2 Operational Features	3-1
3.3 Unit Powering Features.....	3-1
3.4 Input/Output Port Features	3-2
3.5 Mechanical Design Features.....	3-2
3.6 Calibration and Maintenance Features	3-2
3.7 Product Information	3-3
3.7.1 Documentation	3-3
3.7.2 Performance Specification Sheet.....	3-3
3.8 Product Marking and Packaging.....	3-4
3.8.1 Product Marking.....	3-4
3.8.2 Packaging for Shipment from Supplier	3-4
3.9 Safety Features.....	3-4
4. Specific Requirements	4-1
4.1 Operational Criteria.....	4-1
4.1.1 Measurement Range	4-1
4.1.2 Measurement Accuracy.....	4-2
4.1.3 Measurement Time	4-2
4.2 Mechanical Design Criteria	4-2
4.3 Power Criteria.....	4-2
4.4 Environmental Criteria.....	4-2
4.4.1 Non-Operating Environment.....	4-2

4.4.2	Operating Environment.....	4-3
4.4.3	Dust Resistance	4-3
4.5	Safety Criteria.....	4-3
5.	Performance Verification and Test Procedures.....	5-1
5.1	Operational Criteria.....	5-1
5.1.1	Measurement Range	5-1
5.1.2	Measurement Accuracy.....	5-6
5.1.3	Measurement Time.....	5-6
5.2	Mechanical Design Criteria.....	5-7
5.2.1	Shock During Transportation.....	5-7
5.2.2	Shock During Use.....	5-7
5.2.3	Vibration Test.....	5-8
5.3	Power Criteria.....	5-8
5.4	Environmental Criteria.....	5-8
5.4.1	Non-Operating Environment.....	5-8
5.4.2	Operating Environment.....	5-9
5.4.3	Dust Resistance	5-9
5.5	Safety Criteria.....	5-10
6.	References	6-1
6.1	Internal Documents	6-1
6.2	Other References.....	6-2
6.3	Ordering Information	6-2
7.	Glossary	7-1
Appendix 1	Hand-Held OPM General Requirements: Review Results	A1-1
Appendix 2	Hand-Held OPM Performance Verification Test Results.....	A2-1

List of Figures

Figure 5-1.	HHOPM Measurement Range Test Setup: Measurement of MinRP	5-2
Figure 5-2.	HHOPM Measurement Range Test Setup: Measurement of MaxRP...	5-4
Figure 5-3.	Typical HHOPM Received Optical Power Vs Measurement Error Curves	5-5
Figure 5-4.	Dust Resistance Test Setup	5-10

List of Tables

Table 1-1. Characteristics of Typical Telephone Industry Fiber Optic Networks .	2-4
Table 4-1. Response Power Requirements	4-1
Table 4-2. Response Power Objectives	4-1
Table 5-1. Vibration Test Specifications	5-8