

---

# Generic Requirements for Portable Polarization Mode Dispersion (PMD) Test Sets

## Contents

Preface .....	Preface-1
1. Introduction .....	1-1
1.1 Purpose and Scope .....	1-1
1.2 Organization .....	1-1
1.3 Requirements Terminology .....	1-1
1.4 Requirement Labeling Conventions.....	1-2
1.4.1 Numbering of Requirement and Related Objects .....	1-2
1.4.2 Requirement, Conditional Requirement, and Objective Object Identification .....	1-3
2. GENERAL INFORMATION .....	2-1
2.1 Polarization Mode Dispersion.....	2-1
2.1.1 Causes of Birefringence and PMD.....	2-1
2.1.2 Birefringence Related to PMD .....	2-2
2.1.3 Mode Coupling .....	2-3
2.1.4 PMD and Pulse Broadening.....	2-5
2.1.5 Statistical Aspects .....	2-6
2.1.6 PMD Limitations in Digital Systems .....	2-9
2.2 Measurement of PMD .....	2-10
2.2.1 General .....	2-10
2.2.2 The Fixed Analyzer Method .....	2-11
2.2.3 The Jones Matrix Method .....	2-12
2.2.4 The Interferometric Method.....	2-13
2.3 Product Description .....	2-14
3. Design Criteria .....	3-1
3.1 Display and Control Features .....	3-1
3.2 Operation .....	3-3
3.3 Mechanical Design.....	3-4
3.4 Maintenance .....	3-5
3.5 Product Information .....	3-6
3.5.1 Documentation .....	3-6
3.5.2 Performance Specification Sheet .....	3-6
3.6 Product and Packaging Markings.....	3-7
3.6.1 Product Markings .....	3-7
3.6.2 Packaging Markings.....	3-8
3.7 Laser Protection .....	3-8

---

4.	Operational/Environmental Requirements.....	4-1
4.1	Operation.....	4-2
4.1.1	Measurement Accuracy.....	4-2
4.1.2	Measurement Repeatability.....	4-2
4.1.3	Measurement Range.....	4-2
4.1.4	Minimum Test Fiber Length.....	4-2
4.1.5	Measurement Time.....	4-2
4.2	Mechanical Design.....	4-3
4.2.1	Shock Tests.....	4-3
4.2.1.1	Shipment from Manufacturer.....	4-3
4.2.1.2	Local Transportation.....	4-3
4.2.1.3	During Use.....	4-3
4.2.2	Vibration Test.....	4-4
4.3	Power.....	4-4
4.4	Environment.....	4-4
4.5	Electromagnetic Interference and Electrostatic Discharge.....	4-4
4.5.1	Electromagnetic Interference.....	4-4
4.5.2	Electrostatic Discharge.....	4-5
4.6	Protection.....	4-5
4.6.1	Grounding.....	4-5
4.6.2	Leakage Current.....	4-5
4.6.3	Hot Surfaces.....	4-5
5.	Performance Test Procedures.....	5-1
5.1	Operation.....	5-1
5.1.1	Measurement Accuracy.....	5-1
5.1.2	Measurement Repeatability.....	5-2
5.1.3	Measurement Range.....	5-3
5.1.4	Minimum Fiber Length.....	5-3
5.1.5	Measurement Time.....	5-3
5.2	Mechanical Design.....	5-3
5.2.1	Shock Tests.....	5-3
5.2.1.1	Shipment from Manufacturer.....	5-3
5.2.1.2	Local Transportation.....	5-4
5.2.1.3	During Use.....	5-4
5.2.2	Vibration Test.....	5-5
5.3	Power.....	5-5
5.4	Environment.....	5-5
5.4.1	Non-Operating Environment.....	5-5
5.4.2	Operating Environment.....	5-6
5.5	Electromagnetic Interference and Electrostatic Discharge.....	5-6
5.5.1	Electromagnetic Interference.....	5-6
5.5.2	Electrostatic Discharge.....	5-6
5.6	Protection.....	5-6
5.6.1	Grounding.....	5-6

---

5.6.2	Leakage Current.....	5-7
5.6.3	Hot Surfaces.....	5-7
References	.....	References-1
Glossary	.....	Glossary-1



## List of Figures

Figure 2-1.	Random Orientation of the Local Fast (F) and Slow (S) Polarization Axes Along a Fiber Length.....	2-1
Figure 2-2.	Causes of Birefringence in Optical Fiber .....	2-2
Figure 2-3.	PMD vs. Length for the Fibers of Table 2-1 .....	2-4
Figure 2-4.	PMD Effects on a Narrow Impulse in two Source-Coherence Regions...	2-5
Figure 2-5.	Normalized Maxwellian Probability Distribution of the PMD .....	2-7
Figure 2-6.	Minutes Per Year that the Instantaneous PMD Exceeds a Particular Value .....	2-8
Figure 2-7.	PMD-Limited Lengths vs. PMD Coefficient for Two Values of Bit-Rate B and of Bit-Period Fraction f .....	2-10
Figure 2-8.	Schematic Wavelength Scans for Cable in Two Limits of Mode Coupling.....	2-12
Figure 2-9.	Instantaneous PMD vs. Wavelength.....	2-13
Figure 2-10.	Schematic Interferometric Scans for Cable in Two Limits of Mode Coupling.....	2-14
Figure 5-1.	Measurement Accuracy Test Setup .....	5-2



## List of Tables

Table 2-1.	Effect of Mode Coupling Versus Length .....	2-3
Table 4-1.	Drop Test Heights.....	4-3
Table 4-2.	Environmental Extreme Requirements.....	4-4
Table 5-1.	Drop Test Heights.....	5-4
Table 5-2.	Vibration Test Parameters .....	5-5
Table 5-3.	Environmental Extreme Requirements.....	5-5