

Contents

[Telcordia GR-765-Documentation Information](#)

Generic Requirements Notice of Disclaimer	iii
Contents	v
List of Figures	ix
List of Tables	xi
Preface	xiii
About GR-765-CORE	xv
To Submit Comments	xv
1. Introduction	1-1
1.1 Purpose and Scope	1-1
1.2 Changes from TR-NWT-000765, Issue 2	1-1
1.3 Structure and Use of This Document	1-6
1.4 Requirements Terminology	1-6
1.5 Requirement Labeling Conventions	1-7
1.5.1 Numbering of Requirement and Related Objects	1-7
1.5.2 Requirement, Conditional Requirement, and Objective Object Identification	1-8
2. General Information	2-1
2.1 Types of Splicing Systems	2-1
2.1.1 Fusion Splicing	2-1
2.1.2 Mechanical Splicing	2-2
2.2 Applicable Work Conditions	2-3
2.3 Manufacturer's Data	2-3
2.4 Product Analysis	2-4
3. General Requirements and Objectives	3-1
3.1 Documentation	3-1
3.1.1 Practices	3-1
3.1.2 Workcenter Information Package	3-1
3.1.3 Safety	3-2
3.1.4 Compatibility With Other Systems	3-2
3.1.5 Fiber Preparation/Storage	3-2
3.1.6 Adhesives	3-3
3.2 General Splice Criteria	3-3
3.2.1 Dimensions	3-3
3.2.2 Interface with Optical Fibers	3-3
3.2.3 Environmental Sealing	3-4
3.2.4 Strain Relief	3-5
3.2.5 Closed Splice	3-5
3.2.6 Universal Installation	3-6
3.3 Marking, Packaging, and Shipping	3-7
3.3.1 Marking	3-7
3.3.2 Package Label	3-8
3.3.3 Packaging and Shipping	3-9

4. Features, Functions, Performance Criteria	4-1
4.1 Equipment: General Requirements and Objectives	4-1
4.1.1 Portability	4-1
4.1.2 Carrying Case	4-2
4.1.3 Surface Finish and Markings	4-2
4.1.4 Display and Controls	4-3
4.1.5 Fiber Contacting Devices	4-6
4.1.6 Features	4-6
4.1.7 Product Information	4-20
4.2 Splice Optical Criteria	4-21
4.2.1 Mean Splice Loss	4-22
4.2.2 Splice Yield	4-23
4.2.3 Splice Reflectance Criteria	4-24
4.2.4 Sensitivity to Fiber Geometry	4-25
4.3 Fusion Splice Strength Criteria	4-27
4.4 Equipment: Mechanical and Storage Environments Criteria	4-27
4.4.1 Initial Operation	4-27
4.4.2 Cleave Angle Tolerance	4-28
4.4.3 Shock	4-29
4.4.4 Vibration, Transportation	4-30
4.4.5 Storage Environment	4-30
4.5 Equipment: Electrical Requirements	4-30
4.5.1 AC-Powered Equipment	4-31
4.5.2 Battery Unit	4-31
4.5.3 Battery Operation	4-32
4.5.4 Electromagnetic Compatibility	4-35
4.6 Materials and Consumables Criteria	4-35
4.6.1 Coefficient of Thermal Expansion (CTE)	4-36
4.6.2 Toxicity	4-36
4.6.3 Fungus Resistance	4-36
4.6.4 Shelf Life	4-37
4.6.5 Index Matching Material	4-37
4.7 Fiber Splicing - Installation Conditions	4-40
4.7.1 Low Temperature Installation Criteria	4-40
4.7.2 High Temperature and High Humidity Installation Criteria	4-40
4.7.3 High Temperature, Low Humidity Installation Criteria	4-41
4.7.4 High Altitude	4-41
4.7.5 Electrode Wear	4-42
4.7.6 Vibration During Operation	4-43
4.8 Mechanical Splice Environmental Life Test Criteria	4-43
4.8.1 Splice Strength	4-43
4.8.2 Vibration Splice Loss	4-44
4.8.3 Temperature Cycling	4-44
4.8.4 Humidity/Condensation Cycling	4-45
4.8.5 Effect of Immersion on Splice Performance	4-46
4.8.6 Strength After Environmental Degradation	4-47

5. Performance Verification and Test Procedures	5-1
5.1 General Information	5-1
5.1.1 Selection of Optical Fiber	5-1
5.1.2 Selecting the Test Product	5-2
5.1.3 Instructions and Training	5-2
5.1.4 Test Methods	5-2
5.1.5 Experimental Error	5-9
5.1.6 Mechanical Splice and Consumables Conditioning	5-9
5.2 Product Analysis Procedures	5-10
5.2.1 Splicing Test Series A - As Received, Storage, Handling	5-10
5.2.2 Splicing Test Series B - Installation and Assembly Conditions	5-13
5.2.3 Splicing Test Series C - Environmental Life Testing	5-17
5.3 Splicing Equipment - Battery Tests	5-25
5.3.1 Battery Life (Without Heat-Shrink)	5-25
5.3.2 Battery Life (With Heat-Shrink)	5-26
5.4 Fiber Splice Performance Parameters	5-26
5.4.1 Mean Splice Loss	5-26
5.4.2 Splice Yield	5-26
5.4.3 Reflectance	5-27
5.4.4 Splice Strength	5-27
5.4.5 Torsional Test	5-28
5.4.6 Splice Fiber Damage Test	5-30
References	References-1
Glossary	Glossary-1
Requirement-Object Index	ROI-1

List of Figures

Figure 2-1	Schematic of Fusion Splicing Process	2-1
Figure 2-2	Schematic of Mechanical Splices	2-2
Figure 3-1	Fiber Clamp and Guard Arrangements for Taut Sheath Environment vs. Optimum Visibility	3-7
Figure 4-1	Schematic of Arc Test (Meltback Test)	4-16
Figure 4-2	Effect of Cleave Angle and Arc Duration on Fusion Splice Loss . .	4-29
Figure 5-1	Transmission Measurement Test Facility	5-3
Figure 5-2	Description of OTDR Measurement Test Facility	5-6
Figure 5-3	Automated OTDR Measurement Test Facility	5-7
Figure 5-4	Key OTDR Reflectance Parameters	5-8
Figure 5-5	Temperature Cycling Profiles	5-21
Figure 5-6	Temperature/Humidity Profile for Humidity/Condensation Test . .	5-22
Figure 5-7	Tensile Load Test Setup	5-28
Figure 5-8	Schematic of Torsion Test	5-29
Figure 5-9	Schematic View of Splice and Area of Possible Fiber Damage . . .	5-31
Figure 5-10	Supported Fiber Technique	5-32
Figure 5-11	Effects of Fiber Handling Technique on Breaking Load	5-33
Figure 5-12	Effects of Grip Mechanism	5-33

List of Tables

Table 5-1	Splice and Material Conditioning	5-9
Table 5-2	Splicing Test Series A	5-11
Table 5-3	Splicing Test Series B - Assembly Conditions	5-14
Table 5-4	Splicing Test Series C - Environmental Life Test	5-17
Table 5-5	Optical Measurement Sequence for Environmental Life Test	5-18
Table 5-6	Optical Criteria Applied During Environmental Life Test	5-19
Table 5-7	Full Temperature Cycling Profile: Taking Measurements	5-20
Table 5-8	Temperature Cycling Profile: Accelerated Mode	5-21
Table 5-9	Temperature/Humidity Profile for Humidity/Condensation Test	5-22
Table 5-10	Organisms Exposure for Bulk Mineral Oil-based Material	5-23
Table 5-11	Organism Exposure for Completed Splices	5-24
Table 5-12	Calculation Points for Mean Splice Loss	5-26
Table 5-13	Calculation Points for Splice Yield	5-27