

BELLCORE-STD-100 and BELLCORE-STD-200 Inspection Resource Allocation Plans

Contents

1. Introduction.....	1-1
2. Executive Overview.....	2-1
2.1 The Sampling Rate.....	2-1
2.2 Fraction of Lots Sampled.....	2-1
2.3 Feedback to the Supplier.....	2-2
3. BELLCORE-STD-100.....	3-1
3.1 Parameters.....	3-2
3.2 Determining the Parameters.....	3-2
3.2.1 Budget Control Factor (B).....	3-3
3.3 Calculations.....	3-3
3.4 Example.....	3-5
4. BELLCORE-STD-200.....	4-1
4.1 Parameters.....	4-2
4.2 Dependence on System Size (N).....	4-3
4.3 Implementation.....	4-4
4.4 Example.....	4-4
5. Quality Measurement Plan (QMP) Algorithm.....	5-1
5.1 Acceptance Number (c).....	5-1
Appendix A: Quality Measurement Plan (QMP).....	A-1
Appendix B: Sample Budget Factor Calculation.....	B-1

List of Figures

Figure 1.	Sampling Rate Chart Example for BELLCORE-STD-100	3-5
Figure 2.	Feedback Model	3-7
Figure 3.	Sampling Table Example.....	3-8
Figure 4.	Acceptance Numbers	3-10